ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0789, W0428, W0775, W0779, W0773, W0785, W0793, W	NA, Gear College, Munireddy Lyt Rd, Mariyappa Lyt Rd	near Shri Bramhalingeshwara Upahara
Segment No.	**Total Length (m)**	
3/C-W0789/S102204	276.35	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	5.88	77.544598	13.094898	77.544649	13.094880	W0428	W0428
2	5.61	77.544332	13.094989	77.544380	13.094971	W0428	W0428
3	6.71	77.545228	13.094660	77.545287	13.094642	W0428	W0428
4	6.44	77.544740	13.094822	77.544796	13.094804	W0428	W0428
5	8.00	77.544426	13.094921	77.544496	13.094898	W0428	W0428
6	6.80	77.544120	13.095023	77.544179	13.095002	W0428	W0428
7	115.05	77.544450	13.094887	77.544372	13.093850	W0428	W0789
8	121.86	77.544045	13.093892	77.544144	13.094989	W0428	W0789

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Development and Improvement to Roads and Drains in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone	2500000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	Other work type is WBM & CLUVERT
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Development and Improvement to Roads and Drains in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone	003-16-000027
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE (YNK.D) /WO/86/2016-17	01/08/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/11/2016	29/11/2017	Yes

Certified AE-03

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
12		CHANDRAKANTH
Date of Inspection	**Remarks**	
01/08/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0789, W0428, W0775, W0779,

AE-03